WDSC 422 Homework-Assignment 1 Time Studies and Production Estimation Harvesting Forest products

Due Date:

Home work assignment

Recently, a portion of the University research forest was harvested using a Timbco fellerbuncher. During the harvesting operation, the felling time of some sampled trees were collected together with its respective DBH. With this given data, develop an equation to estimate felling time per tree for this feller-buncher based on tree size. You need to describe how the model is developed and how good the model is in terms of R^2 , root MSE, and P-value. You also need to include attachments as shown in Figures 3 and 5.

Table 1.

DBH (in.)	Time per tree (min.)
4	0.460
5	0.563
6	0.436
7	0.425
8	0.616
9	0.444
10	0.621
11	0.467
12	0.634
13	0.564
14	0.526
15	0.632
16	0.556
17	0.641
18	0.688
19	0.697
22	0.682

Background

Least squares regression modeling has long been an efficient, accurate method of estimating and predicting forestry data. Estimation involves the calculation parameters of a population (e.g. mean). Developing a production model requires the combination of a variables (dependent and independent) affecting the harvesting activities of a particular machine such as work conditions surrounding harvesting operation like tree size, slope, and other terrain conditions. The procedure for developing harvesting equations is as follows;

- 1. Means calculation
- 2. Plotting data
- 3. Fitting models
- 4. Testing fits

Mean: It gives an overall average of productivity. It is calculated by summing up all individual observations and dividing it by the number of observations.

Plotting data:

- Calculate the average time for each-inch DBH and draw the plot.
- Now, instead of having the overall average time per tree, we have average time for each DBH class
- Investigate outliers before removal from the data set

Fitting the model: The best line of fit is plotted using appropriate software like SAS, MS Excel, or others.

Testing the model:

Procedure for developing equations:

- A. Running your data in MS excel to get means of your variables
 - 1. Type and save data in MS excel
 - 2. Click on "Data analysis" icon on the tool bar
 - 3. Select **Regression** from the dialogue box, click **OK**

C	2						Book1 - I	vlicrosoft Excel						
0	Home	Insert Page La	ayout Formulas	Data Rev	riew View									0
Fr	om From Web	From From Other Text Sources C	Existing Connections All	Connection Properties Edit Links	S AL AZA ZL ZA ZL Sort	Filter	Clear Reapply Advanced	Text to Remov Columns Duplica	re (tes)(ali	Data Consolidate	What-If	Group Un	ngroup Subtotal	Data Analysi
		Get External Data	14	tonnections	JL	SUILOCH	oter	l.		a Anatysis				Artatysis
	1) - (11 -	-							AD E	alysis Tools			ОК	
	D12	- (°	f _x						F-	-Test Two-Sample for	Variances		Cance	
	A	В	С	D	E	F	G	H I	Fo	ourier Analysis istogram				P
1									M	loving Average			Help	
	DBH	Fell time (min)	Processing (min)	Cycle					Ra	andom Number Genera ank and Percentile	ation			
2									R	egression				
3	10	0.9	0.7	1.6					58 t-1	ampling Test: Paired Two Sam	ple for Means	5	~	
4	8	0.5	0.5	1										
5	12	0.8	1	1.8										
6	18	1.2	1	2.2										
7	95	0.6	01	0.7										
8	11.5	0.8	0.66	1.46										

Figure 1.

4. Time "Input Y Range" box and Dbh values into "Input X Range:" box

0	2						Bo	ok1 - Micro	soft Excel						
0	Home	Insert Page Li	ayout Formulas	Data	teview \	'iew									
Fr	om From Fro cess Web Te Ge	m From Other kt Sources C	Existing Connections	Connecti Propertie Edit Links	ons s ⊉↓ [∡↓	Sort Sort 8	er <u>J</u> Adv Filter	ar ppply ranced Colu	t to Remo	ove Dat ates Validat Data	ta Conso tion * Tools	lidate What Analys	-If Group	Ungroup S Outline	iubtotal
	127 - Cal =														
-	D12	- (0	f _x												
	А	В	С	D	E	F	G	Н	- I	J	К	L	M	N	0
1	DBH	Fell time (min)	Processing (min)	Cycle	Regress	ion					? 🛛				
З	10	0.9	0.7	1.6	Input	(Range:		\$D\$3:\$D\$8	1		OK				
4	8	0.5	0.5	1	Input 3	Range:		\$443.4448	56	Ca	ancel				
5	12	0.8	1	1.8	an proving	T. ranger		puto puto	(1489)		leln				
6	18	1.2	1	2.2	La	bels		Constant is Zer)						
7	9.5	0.6	0.1	0.7	V Co	n <u>t</u> idence Lev	el: 95	%							
8	11.5	0.8	0.66	1.46	Output	options									
9					0 <u>Q</u> u	tput Range:			1						
10					 Ner 	w Worksheet	Elv:								
12				r	O Ner	w <u>W</u> orkbook					-				
13					Residu	als									
14						siduals odardized Re	esiduals	Line Fit	Plots Plots						
15					Dia:	Deckshills									
16					Norma No	mal Probabili	ty Plots								
17															
18							1			1					

Figure 2.

5. Check confidence level box, Residual plot, Line fit plot and normal probability plots. Finally click OK

Home Inser	t Page Layout	Formulas	Data	Review	View	Bo	okl - Micr	osoft Excel									6	
👻 🔏 Cut	Calibri	• 11 • A*	, ·) (= ;	= - &	-	an Text	Gener	al	-			1		× =	ΣΑ	utoSum *	Az a	A
Eormat Painte	B I U -	E - 🖄 - 🛓			E Me	rge & Cente	r - \$ -	% ,	00 0	Inditional	Format Ce	ell In	isert De	lete Forr	nat C	ll -	Sort & Fir	nd &
Clipboard	Fi Fi	ont	154	Ali	gnment		15	Number	Fa F	St	yles		C	ells		Ed	iting	eu
u) - (u																		
D10																		
А	В	С	D	E	F	G	Н	1	J	K	L	M		N	0	Р	Q	
SUMMARY OUTPUT	r ^o											-						
										X Va	riable 1	Res	sidua	al Plo	t			
Regression S	Statistics									0.5								
Multiple R	0.833697058												•					
R Square	0.695050784								물	0	Č.	•	•	- C	•			
Adjusted R Square	0.61881348								sidu	0	5	1	0	15	20			
Standard Error	0.334994495								Re	-0.5 -		٠						
Observations	6																	
										-1 -		XVaria	able 1					
ANOVA																		
	df	SS	MS	F	Sig. F											_		
Regression	1	1.023114754	1.023115	9.116938	0.039185					XVa	ariable	1 Lin	e Fit	Plot	-			
Residual	4	0.448885246	0.112221								indusie	III	e i iii	1 101				
Total	5	1.472																
									25									
	Coefficients	S. Error	t Stat	P-value	ower 95%	Jpper 95%	ower 95.09	pper 95.0%	2 -						Y			
Intercept	-0.029344262	0.51186232	-0.05733	0.957033	-1.4505	1.391813	-1.4505	1.391813	1.5			-			Due diete d V	_		
X Variable 1	0.129508197	0.04289165	3.019427	0.039185	0.010422	0.248595	0.010422	0.248595	05						Predicted			
									0 -			, .	.					
										10 8	x Variable 1	9.5	11.5					
											A VORIDUCE A	-						
RESIDUAL OUTPUT				PROBABILI	IY OUTPU			[100	2.15	100000	2,555		1		
01	0 1:1 11	2 . 1 . 1		0						Nor	rmal Pr	obab	oility	Plot				
Upservation	Predicted Y	Residuals		Percentile	Y 0.7					3								
1	1.265/3//05	0.006701211		0.5555553	0.7				~	2		_	_					
2	1.000721311	-0.000721311		25 41 66667	1 /5				-	1			-	-				
3	2 301803270	-0 101803370		+1.00007	1.40					0 +								
4	1 200983607	-0.101003275		75	1.0					3333°.	25 6666	3333	15 ,6	60	Series1	-		
5	1.200303007	-2.22045E-16		91,66667	2.0					e.32	A1.0 58	2	92.00					
0	1.40	2.220-02-10		51.00007	2.2						Sample D	Perceptil	le					
											Southly L	crocitta				-		
		11.7																
► ► Sheet4 S	heet1 / Sheet2	/Sheet3 / 💭								4			111				-	

a. Output: your output should look like this:

Figure 3.

B. Extract out the mean of X, Y, and intercept variables together with their P and F-values into a table like the one shown below.

	Coeff.	S.E	t Stat	P-value	Lower 95%	Upper 95%	Lower 95.0%	Upper 95.0%
Intercept	-0.02934	0.59525	-0.0493	0.96378	-1.9237	1.86501	-1.9237	1.86501
DBH	0.129508	0.04952	2.6149	0.07934	0.0281	0.28712	0.0281	0.28712

Computer output of regression results

C. Write out the equation on the form shown below: Equation: Y (average cycle time) = -0.029 + 0.129DBH, R-square 0.69. (1)

- D. Plot the data and include equation developed.
 - 1. Highlight the DBH and time data in your excel spread sheet
 - 2. Click on Scatter from the menu bar, choose scatter with marker option



3. Click on **layout3**, add trend line, line equation, and R² via trend line options dialogue box. (add equations and R-square by checking on the appropriate boxes at the bottom of the trend line dialogue box).



Figure 5.

Data Analysis with Analysis ToolPak

The Analysis ToolPak is an add-in that provides analytical capability that normally is not available. The following analyses are provided by ToolPak:

- Analysis of variance (three types)
- o Correlation
- o Covariance
- Descriptive statistics
- o Exponential smoothing
- o F-test
- Fourier analysis
- o Histogram
- Moving average
- Random number generation
- o Rank and percentile
- o Regression
- o Sampling
- o t-test (three types)
- o z-test

(1) Install and use the Analysis ToolPak

Before using an analysis tool, you must arrange the data you want to analyze in columns or rows on your worksheet. This is your input range. If the **Data Analysis** command is not on the **Tools** menu, you need to install the Analysis ToolPak in Microsoft Excel.

To install the Analysis ToolPak:

- Click the Microsoft Office Button, and then click Excel Options.
- Click Add-Ins, and then in the Manage box, select Excel Add-ins. and hit GO.
- In the Add-Ins available box (Figure 6), select the Analysis ToolPak check box, and then click OK.
- After you load the Analysis ToolPak, the Data Analysis command is available in the Analysis group on the Data tab.

To use the Analysis ToolPak:

- (a) On the **Data** menu, click **Data Analysis** (Figure 7).
- (b) In the **Analysis Tools** box, click the tool you want to use.
- (c) Enter the input range and the output range, and then select the options you want.

To remove an add-in program from Microsoft Excel:

- (a) Click the Microsoft Office Button , and then click Excel Options .
- (b) Click Add-Ins, and then in the Manage box, select Excel Add-ins. and hit GO.
- (c) In the Add-Ins available box, clear the check box next to the add-in you want to unload.
- (d) To remove the add-in from memory, restart Excel.



Figure 6. Add-ins dialog box.



Figure 7. Data analysis dialog box.